

## EMEP – 34<sup>th</sup> intercomparison of analytical methods

Laboratory 15, Norwegian Institute for Air Research NILU (Norway)

### Sulphur dioxide in absorbing solution (A-samples)

Sample name	Determinand	Reported value <sup>¥</sup>	Expected value	Mean value	Standard deviation	Z score	EMEP quality norm <sup>¤</sup>
A2	SO <sub>2</sub>	0.771	0.802	0.779	0.039	-0.199	S
A3	SO <sub>2</sub>	0.807	0.842	0.794	0.02	0.639	S
A4	SO <sub>2</sub>	0.389	0.401	0.387	0.018	0.137	S
A5	SO <sub>2</sub>	0.432	0.441	0.416	0.016	1	S

<sup>¥</sup> Reported values are blank corrected, unless you informed us that this has already been done.  
Corrections are done by subtracting the blank value when a value was reported, or 1/2 MDL when MDL was reported.

<sup>¤</sup> EMEP quality norm; the letters in the column indicates:

S – Satisfactory: Your result deviates less than  $\pm 10\%$  of the expected value

Q – Questionable: Your result deviates between  $\pm 10\text{--}20\%$  of the expected value

U – Unsatisfactory: Your result deviates more than  $\pm 20\%$  of the expected value

B – Blank: You reported either no value or the detection limit

Please check the EMEP intercalibration website for more statistics, Youden plots, updated expected values ect: <http://www.nilu.no/projects/ccc/intercomparison.html>

**Deltaker i CIENS og Framsenteret / Associated with CIENS and the Fram Centre**  
**ISO-sertifisert etter / ISO certified according to NS-EN ISO 9001/ISO 14001**

NILU – Norsk institutt for luftforskning  
PO Box 100  
NO-2027 KJELLER, Norway  
Phone: +47 63 89 80 00/Fax: +47 63 89 80 50  
Besøk/visit: Instituttveien 18, 2007 Kjeller

NILU – Norsk institutt for luftforskning  
Framsenteret / The Fram Centre  
NO-9296 TROMSØ, Norway  
Phone: +47 77 75 03 75/Fax: +47 77 75 03 76  
Besøk/visit: Hjalmar Johansens gt. 14, 9007 Tromsø

e-mail: nilu@nilu.no  
nilu-tromso@nilu.no  
Internet: [www.nilu.no](http://www.nilu.no)  
Bank: 5102.05.19030  
Foretaksnr./Enterprise no. 941705561

## EMEP – 34<sup>th</sup> intercomparison of analytical methods

Laboratory 19, Centro Nacional de Sanidad Ambiental (Spain)

### Sulphur dioxide in absorbing solution (A-samples)

Sample name	Determinand	Reported value <sup>¥</sup>	Expected value	Mean value	Standard deviation	Z score	EMEP quality norm <sup>¤</sup>
A2	SO <sub>2</sub>	0.73	0.802	0.779	0.039	-1.261	S
A3	SO <sub>2</sub>	0.79	0.842	0.794	0.02	-0.194	S
A4	SO <sub>2</sub>	0.35	0.401	0.387	0.018	-2.001	Q
A5	SO <sub>2</sub>	0.4	0.441	0.416	0.016	-1.016	S

<sup>¥</sup> Reported values are blank corrected, unless you informed us that this has already been done.  
Corrections are done by subtracting the blank value when a value was reported, or 1/2 MDL when MDL was reported.

<sup>¤</sup> EMEP quality norm; the letters in the column indicates:

S – Satisfactory: Your result deviates less than  $\pm 10\%$  of the expected value

Q – Questionable: Your result deviates between  $\pm 10\text{--}20\%$  of the expected value

U – Unsatisfactory: Your result deviates more than  $\pm 20\%$  of the expected value

B – Blank: You reported either no value or the detection limit

Please check the EMEP intercalibration website for more statistics, Youden plots, updated expected values ect: <http://www.nilu.no/projects/ccc/intercomparison.html>

**Deltaker i CIENS og Framsenteret / Associated with CIENS and the Fram Centre**  
**ISO-sertifisert etter / ISO certified according to NS-EN ISO 9001/ISO 14001**

NILU – Norsk institutt for luftforskning  
PO Box 100  
NO-2027 KJELLER, Norway  
Phone: +47 63 89 80 00/Fax: +47 63 89 80 50  
Besøk/visit: Instituttveien 18, 2007 Kjeller

NILU – Norsk institutt for luftforskning  
Framsenteret / The Fram Centre  
NO-9296 TROMSØ, Norway  
Phone: +47 77 75 03 75/Fax: +47 77 75 03 76  
Besøk/visit: Hjalmar Johansens gt. 14, 9007 Tromsø

e-mail: nilu@nilu.no  
nilu-tromso@nilu.no  
Internet: [www.nilu.no](http://www.nilu.no)  
Bank: 5102.05.19030  
Foretaksnr./Enterprise no. 941705561

## EMEP – 34<sup>th</sup> intercomparison of analytical methods

Laboratory 20, Swedish Environmental Research Institute IVL, Gothenburg (Sweden)

### Sulphur dioxide in absorbing solution (A-samples)

Sample name	Determinand	Reported value <sup>¥</sup>	Expected value	Mean value	Standard deviation	Z score	EMEP quality norm <sup>¤</sup>
A2	SO <sub>2</sub>	0.784	0.802	0.779	0.039	0.138	S
A3	SO <sub>2</sub>	0.822	0.842	0.794	0.02	1.373	S
A4	SO <sub>2</sub>	0.384	0.401	0.387	0.018	-0.137	S
A5	SO <sub>2</sub>	0.433	0.441	0.416	0.016	1.063	S

<sup>¥</sup> Reported values are blank corrected, unless you informed us that this has already been done.  
Corrections are done by subtracting the blank value when a value was reported, or 1/2 MDL when MDL was reported.

<sup>¤</sup> EMEP quality norm; the letters in the column indicates:

S – Satisfactory: Your result deviates less than  $\pm 10\%$  of the expected value

Q – Questionable: Your result deviates between  $\pm 10\text{--}20\%$  of the expected value

U – Unsatisfactory: Your result deviates more than  $\pm 20\%$  of the expected value

B – Blank: You reported either no value or the detection limit

Please check the EMEP intercalibration website for more statistics, Youden plots, updated expected values ect: <http://www.nilu.no/projects/ccc/intercomparison.html>

**Deltaker i CIENS og Framsenteret / Associated with CIENS and the Fram Centre**  
**ISO-sertifisert etter / ISO certified according to NS-EN ISO 9001/ISO 14001**

NILU – Norsk institutt for luftforskning  
PO Box 100  
NO-2027 KJELLER, Norway  
Phone: +47 63 89 80 00/Fax: +47 63 89 80 50  
Besøk/visit: Instituttveien 18, 2007 Kjeller

NILU – Norsk institutt for luftforskning  
Framsenteret / The Fram Centre  
NO-9296 TROMSØ, Norway  
Phone: +47 77 75 03 75/Fax: +47 77 75 03 76  
Besøk/visit: Hjalmar Johansens gt. 14, 9007 Tromsø

e-mail: nilu@nilu.no  
nilu-tromso@nilu.no  
Internet: [www.nilu.no](http://www.nilu.no)  
Bank: 5102.05.19030  
Foretaksnr./Enterprise no. 941705561

## EMEP – 34<sup>th</sup> intercomparison of analytical methods

**Laboratory 178, Environmental Chemistry and EANET Monitoring Laboratory,Limnological Institute RAS/SB, Irkutsk (Russian Federation)**

### Sulphur dioxide in absorbing solution (A-samples)

Sample name	Determinand	Reported value <sup>¥</sup>	Expected value	Mean value	Standard deviation	Z score	EMEP quality norm <sup>¤</sup>
A2	SO <sub>2</sub>	0.77	0.802	0.779	0.039	-0.225	S
A3	SO <sub>2</sub>	0.804	0.842	0.794	0.02	0.492	S
A4	SO <sub>2</sub>	0.378	0.401	0.387	0.018	-0.466	S
A5	SO <sub>2</sub>	0.417	0.441	0.416	0.016	0.055	S

¥ Reported values are blank corrected, unless you informed us that this has already been done.

Corrections are done by subtracting the blank value when a value was reported, or 1/2 MDL when MDL was reported.

¤ EMEP quality norm; the letters in the column indicates:

S – Satisfactory: Your result deviates less than  $\pm 10\%$  of the expected value

Q – Questionable: Your result deviates between  $\pm 10\text{--}20\%$  of the expected value

U – Unsatisfactory: Your result deviates more than  $\pm 20\%$  of the expected value

B – Blank: You reported either no value or the detection limit

Please check the EMEP intercalibration website for more statistics, Youden plots, updated expected values ect: <http://www.nilu.no/projects/ccc/intercomparison.html>

**Deltaker i CIENS og Framsenteret / Associated with CIENS and the Fram Centre  
ISO-sertifisert etter / ISO certified according to NS-EN ISO 9001/ISO 14001**

NILU – Norsk institutt for luftforskning  
PO Box 100  
NO-2027 KJELLER, Norway  
Phone: +47 63 89 80 00/Fax: +47 63 89 80 50  
Besøk/visit: Instituttveien 18, 2007 Kjeller

NILU – Norsk institutt for luftforskning  
Framsenteret / The Fram Centre  
NO-9296 TROMSØ, Norway  
Phone: +47 77 75 03 75/Fax: +47 77 75 03 76  
Besøk/visit: Hjalmar Johansens gt. 14, 9007 Tromsø

e-mail: nilu@nilu.no  
nilu-tromso@nilu.no  
Internet: [www.nilu.no](http://www.nilu.no)  
Bank: 5102.05.19030  
Foretaksnr./Enterprise no. 941705561

## EMEP – 34<sup>th</sup> intercomparison of analytical methods

Laboratory 183, Public health institute Uzice (Republic of Serbia)

### Sulphur dioxide in absorbing solution (A-samples)

Sample name	Determinand	Reported value <sup>¥</sup>	Expected value	Mean value	Standard deviation	Z score	EMEP quality norm <sup>¤</sup>
A2	SO <sub>2</sub>	0.773	0.802	0.779	0.039	-0.134	S
A3	SO <sub>2</sub>	0.805	0.842	0.794	0.02	0.565	S
A4	SO <sub>2</sub>	0.379	0.401	0.387	0.018	-0.438	S
A5	SO <sub>2</sub>	0.414	0.441	0.416	0.016	-0.102	S

<sup>¥</sup> Reported values are blank corrected, unless you informed us that this has already been done.  
 Corrections are done by subtracting the blank value when a value was reported, or 1/2 MDL when MDL was reported.

<sup>¤</sup> EMEP quality norm; the letters in the column indicates:

- S – Satisfactory: Your result deviates less than  $\pm 10\%$  of the expected value
- Q – Questionable: Your result deviates between  $\pm 10\text{--}20\%$  of the expected value
- U – Unsatisfactory: Your result deviates more than  $\pm 20\%$  of the expected value
- B – Blank: You reported either no value or the detection limit

Please check the EMEP intercalibration website for more statistics, Youden plots, updated expected values ect: <http://www.nilu.no/projects/ccc/intercomparison.html>

**Deltaker i CIENS og Framsenteret / Associated with CIENS and the Fram Centre**  
**ISO-sertifisert etter / ISO certified according to NS-EN ISO 9001/ISO 14001**

NILU – Norsk institutt for luftforskning  
 PO Box 100  
 NO-2027 KJELLER, Norway  
 Phone: +47 63 89 80 00/Fax: +47 63 89 80 50  
 Besøk/visit: Instituttveien 18, 2007 Kjeller

NILU – Norsk institutt for luftforskning  
 Framsenteret / The Fram Centre  
 NO-9296 TROMSØ, Norway  
 Phone: +47 77 75 03 75/Fax: +47 77 75 03 76  
 Besøk/visit: Hjalmar Johansens gt. 14, 9007 Tromsø

e-mail: nilu@nilu.no  
 nilu-tromso@nilu.no  
**Internet:** [www.nilu.no](http://www.nilu.no)  
 Bank: 5102.05.19030  
 Foretaksnr./Enterprise no. 941705561

## EMEP – 34<sup>th</sup> intercomparison of analytical methods

Laboratory 184, Institute for Public Health Pozarevac (Republic of Serbia)

### Sulphur dioxide in absorbing solution (A-samples)

Sample name	Determinand	Reported value <sup>¥</sup>	Expected value	Mean value	Standard deviation	Z score	EMEP quality norm <sup>¤</sup>
A2	SO <sub>2</sub>	0.766	0.802	0.779	0.039	-0.328	S
A3	SO <sub>2</sub>	0.786	0.842	0.794	0.02	-0.389	S
A4	SO <sub>2</sub>	0.387	0.401	0.387	0.018	0.027	S
A5	SO <sub>2</sub>	0.405	0.441	0.416	0.016	-0.701	S

¥ Reported values are blank corrected, unless you informed us that this has already been done.  
 Corrections are done by subtracting the blank value when a value was reported, or 1/2 MDL when MDL was reported.

¤ EMEP quality norm; the letters in the column indicates:

S – Satisfactory: Your result deviates less than  $\pm 10\%$  of the expected value

Q – Questionable: Your result deviates between  $\pm 10\text{--}20\%$  of the expected value

U – Unsatisfactory: Your result deviates more than  $\pm 20\%$  of the expected value

B – Blank: You reported either no value or the detection limit

Please check the EMEP intercalibration website for more statistics, Youden plots, updated expected values ect: <http://www.nilu.no/projects/ccc/intercomparison.html>

**Deltaker i CIENS og Framsenteret / Associated with CIENS and the Fram Centre**  
**ISO-sertifisert etter / ISO certified according to NS-EN ISO 9001/ISO 14001**

NILU – Norsk institutt for luftforskning  
 PO Box 100  
 NO-2027 KJELLER, Norway  
 Phone: +47 63 89 80 00/Fax: +47 63 89 80 50  
 Besøk/visit: Instituttveien 18, 2007 Kjeller

NILU – Norsk institutt for luftforskning  
 Framsenteret / The Fram Centre  
 NO-9296 TROMSØ, Norway  
 Phone: +47 77 75 03 75/Fax: +47 77 75 03 76  
 Besøk/visit: Hjalmar Johansens gt. 14, 9007 Tromsø

e-mail: nilu@nilu.no  
 nilu-tromsø@nilu.no  
**Internet:** [www.nilu.no](http://www.nilu.no)  
 Bank: 5102.05.19030  
 Foretaksnr./Enterprise no. 941705561

## EMEP – 34<sup>th</sup> intercomparison of analytical methods

**Laboratory 188, Institute of Public Health - Krusevac (Republic of Serbia)**

### Sulphur dioxide in absorbing solution (A-samples)

Sample name	Determinand	Reported value <sup>¥</sup>	Expected value	Mean value	Standard deviation	Z score	EMEP quality norm <sup>¤</sup>
A2	SO <sub>2</sub>	0.757	0.802	0.779	0.039	-0.561	S
A3	SO <sub>2</sub>	0.81	0.842	0.794	0.02	0.785	S
A4	SO <sub>2</sub>	0.379	0.401	0.387	0.018	-0.411	S
A5	SO <sub>2</sub>	0.417	0.441	0.416	0.016	0.055	S

<sup>¥</sup> Reported values are blank corrected, unless you informed us that this has already been done.  
 Corrections are done by subtracting the blank value when a value was reported, or 1/2 MDL when MDL was reported.

<sup>¤</sup> EMEP quality norm; the letters in the column indicates:

S – Satisfactory: Your result deviates less than  $\pm 10\%$  of the expected value

Q – Questionable: Your result deviates between  $\pm 10\text{--}20\%$  of the expected value

U – Unsatisfactory: Your result deviates more than  $\pm 20\%$  of the expected value

B – Blank: You reported either no value or the detection limit

Please check the EMEP intercalibration website for more statistics, Youden plots, updated expected values ect: <http://www.nilu.no/projects/ccc/intercomparison.html>

**Deltaker i CIENS og Framsenteret / Associated with CIENS and the Fram Centre**  
**ISO-sertifisert etter / ISO certified according to NS-EN ISO 9001/ISO 14001**

NILU – Norsk institutt for luftforskning  
 PO Box 100  
 NO-2027 KJELLER, Norway  
 Phone: +47 63 89 80 00/Fax: +47 63 89 80 50  
 Besøk/visit: Instituttveien 18, 2007 Kjeller

NILU – Norsk institutt for luftforskning  
 Framsenteret / The Fram Centre  
 NO-9296 TROMSØ, Norway  
 Phone: +47 77 75 03 75/Fax: +47 77 75 03 76  
 Besøk/visit: Hjalmar Johansens gt. 14, 9007 Tromsø

e-mail: nilu@nilu.no  
 nilu-tromsø@nilu.no  
 Internet: [www.nilu.no](http://www.nilu.no)  
 Bank: 5102.05.19030  
 Foretaksnr./Enterprise no. 941705561

## EMEP – 34<sup>th</sup> intercomparison of analytical methods

Laboratory 189, Institute of Public Health - Kikinda (Republic of Serbia)

### Sulphur dioxide in absorbing solution (A-samples)

Sample name	Determinand	Reported value <sup>¥</sup>	Expected value	Mean value	Standard deviation	Z score	EMEP quality norm <sup>¤</sup>
A2	SO <sub>2</sub>	0.761	0.802	0.779	0.039	-0.458	S
A3	SO <sub>2</sub>	0.774	0.842	0.794	0.02	-0.977	S
A4	SO <sub>2</sub>	0.384	0.401	0.387	0.018	-0.137	S
A5	SO <sub>2</sub>	0.421	0.441	0.416	0.016	0.307	S

¥ Reported values are blank corrected, unless you informed us that this has already been done.  
Corrections are done by subtracting the blank value when a value was reported, or 1/2 MDL when MDL was reported.

¤ EMEP quality norm; the letters in the column indicates:

S – Satisfactory: Your result deviates less than  $\pm 10\%$  of the expected value

Q – Questionable: Your result deviates between  $\pm 10\text{--}20\%$  of the expected value

U – Unsatisfactory: Your result deviates more than  $\pm 20\%$  of the expected value

B – Blank: You reported either no value or the detection limit

Please check the EMEP intercalibration website for more statistics, Youden plots, updated expected values ect: <http://www.nilu.no/projects/ccc/intercomparison.html>

**Deltaker i CIENS og Framsenteret / Associated with CIENS and the Fram Centre**  
**ISO-sertifisert etter / ISO certified according to NS-EN ISO 9001/ISO 14001**

NILU – Norsk institutt for luftforskning  
PO Box 100  
NO-2027 KJELLER, Norway  
Phone: +47 63 89 80 00/Fax: +47 63 89 80 50  
Besøk/visit: Instituttveien 18, 2007 Kjeller

NILU – Norsk institutt for luftforskning  
Framsenteret / The Fram Centre  
NO-9296 TROMSØ, Norway  
Phone: +47 77 75 03 75/Fax: +47 77 75 03 76  
Besøk/visit: Hjalmar Johansens gt. 14, 9007 Tromsø

e-mail: nilu@nilu.no  
nilu-tromso@nilu.no  
Internet: [www.nilu.no](http://www.nilu.no)  
Bank: 5102.05.19030  
Foretaksnr./Enterprise no. 941705561

## EMEP – 34<sup>th</sup> intercomparison of analytical methods

Laboratory 193, Institute of Public Health of Vojvodina (Republic of Serbia)

### Sulphur dioxide in absorbing solution (A-samples)

Sample name	Determinand	Reported value <sup>¥</sup>	Expected value	Mean value	Standard deviation	Z score	EMEP quality norm <sup>¤</sup>
A2	SO <sub>2</sub>	0.82	0.802	0.779	0.039	1.07	S
A3	SO <sub>2</sub>	0.78	0.842	0.794	0.02	-0.683	S
A4	SO <sub>2</sub>	0.39	0.401	0.387	0.018	0.192	S
A5	SO <sub>2</sub>	0.42	0.441	0.416	0.016	0.244	S

<sup>¥</sup> Reported values are blank corrected, unless you informed us that this has already been done.  
 Corrections are done by subtracting the blank value when a value was reported, or 1/2 MDL when MDL was reported.

<sup>¤</sup> EMEP quality norm; the letters in the column indicates:

S – Satisfactory: Your result deviates less than  $\pm 10\%$  of the expected value

Q – Questionable: Your result deviates between  $\pm 10\text{--}20\%$  of the expected value

U – Unsatisfactory: Your result deviates more than  $\pm 20\%$  of the expected value

B – Blank: You reported either no value or the detection limit

Please check the EMEP intercalibration website for more statistics, Youden plots, updated expected values ect: <http://www.nilu.no/projects/ccc/intercomparison.html>

**Deltaker i CIENS og Framsenteret / Associated with CIENS and the Fram Centre**  
**ISO-sertifisert etter / ISO certified according to NS-EN ISO 9001/ISO 14001**

NILU – Norsk institutt for luftforskning  
 PO Box 100  
 NO-2027 KJELLER, Norway  
 Phone: +47 63 89 80 00/Fax: +47 63 89 80 50  
 Besøk/visit: Instituttveien 18, 2007 Kjeller

NILU – Norsk institutt for luftforskning  
 Framsenteret / The Fram Centre  
 NO-9296 TROMSØ, Norway  
 Phone: +47 77 75 03 75/Fax: +47 77 75 03 76  
 Besøk/visit: Hjalmar Johansens gt. 14, 9007 Tromsø

e-mail: nilu@nilu.no  
 nilu-tromsø@nilu.no  
 Internet: [www.nilu.no](http://www.nilu.no)  
 Bank: 5102.05.19030  
 Foretaksnr./Enterprise no. 941705561

## EMEP – 34<sup>th</sup> intercomparison of analytical methods

Laboratory 194, Institute of Public Health - Zrenjanin (Republic of Serbia)

### Sulphur dioxide in absorbing solution (A-samples)

Sample name	Determinand	Reported value <sup>¥</sup>	Expected value	Mean value	Standard deviation	Z score	EMEP quality norm <sup>¤</sup>
A2	SO <sub>2</sub>	0.758	0.802	0.779	0.039	-0.536	S
A3	SO <sub>2</sub>	0.805	0.842	0.794	0.02	0.541	S
A4	SO <sub>2</sub>	0.412	0.401	0.387	0.018	1.398	S
A5	SO <sub>2</sub>	0.445	0.441	0.416	0.016	1.819	S

<sup>¥</sup> Reported values are blank corrected, unless you informed us that this has already been done.  
Corrections are done by subtracting the blank value when a value was reported, or 1/2 MDL when MDL was reported.

<sup>¤</sup> EMEP quality norm; the letters in the column indicates:

S – Satisfactory: Your result deviates less than  $\pm 10\%$  of the expected value

Q – Questionable: Your result deviates between  $\pm 10\text{--}20\%$  of the expected value

U – Unsatisfactory: Your result deviates more than  $\pm 20\%$  of the expected value

B – Blank: You reported either no value or the detection limit

Please check the EMEP intercalibration website for more statistics, Youden plots, updated expected values ect: <http://www.nilu.no/projects/ccc/intercomparison.html>

**Deltaker i CIENS og Framsenteret / Associated with CIENS and the Fram Centre**  
**ISO-sertifisert etter / ISO certified according to NS-EN ISO 9001/ISO 14001**

NILU – Norsk institutt for luftforskning  
PO Box 100  
NO-2027 KJELLER, Norway  
Phone: +47 63 89 80 00/Fax: +47 63 89 80 50  
Besøk/visit: Instituttveien 18, 2007 Kjeller

NILU – Norsk institutt for luftforskning  
Framsenteret / The Fram Centre  
NO-9296 TROMSØ, Norway  
Phone: +47 77 75 03 75/Fax: +47 77 75 03 76  
Besøk/visit: Hjalmar Johansens gt. 14, 9007 Tromsø

e-mail: nilu@nilu.no  
nilu-tromso@nilu.no  
Internet: [www.nilu.no](http://www.nilu.no)  
Bank: 5102.05.19030  
Foretaksnr./Enterprise no. 941705561

## EMEP – 34<sup>th</sup> intercomparison of analytical methods

Laboratory 203, The Public Health Institute Vranje (Republic of Serbia)

### Sulphur dioxide in absorbing solution (A-samples)

Sample name	Determinand	Reported value <sup>¥</sup>	Expected value	Mean value	Standard deviation	Z score	EMEP quality norm <sup>¤</sup>
A2	SO <sub>2</sub>	0.9	0.802	0.779	0.039	3.141	Q
A3	SO <sub>2</sub>	0.75	0.842	0.794	0.02	-2.151	Q
A4	SO <sub>2</sub>	0.42	0.401	0.387	0.018	1.836	S
A5	SO <sub>2</sub>	0.39	0.441	0.416	0.016	-1.645	Q

¥ Reported values are blank corrected, unless you informed us that this has already been done.  
Corrections are done by subtracting the blank value when a value was reported, or 1/2 MDL when MDL was reported.

¤ EMEP quality norm; the letters in the column indicates:

S – Satisfactory: Your result deviates less than ±10% of the expected value

Q – Questionable: Your result deviates between ±10-20% of the expected value

U – Unsatisfactory: Your result deviates more than ±20% of the expected value

B – Blank: You reported either no value or the detection limit

Please check the EMEP intercalibration website for more statistics, Youden plots, updated expected values ect: <http://www.nilu.no/projects/ccc/intercomparison.html>

**Deltaker i CIENS og Framsenteret / Associated with CIENS and the Fram Centre**  
**ISO-sertifisert etter / ISO certified according to NS-EN ISO 9001/ISO 14001**

NILU – Norsk institutt for luftforskning  
PO Box 100  
NO-2027 KJELLER, Norway  
Phone: +47 63 89 80 00/Fax: +47 63 89 80 50  
Besøk/visit: Instituttveien 18, 2007 Kjeller

NILU – Norsk institutt for luftforskning  
Framsenteret / The Fram Centre  
NO-9296 TROMSØ, Norway  
Phone: +47 77 75 03 75/Fax: +47 77 75 03 76  
Besøk/visit: Hjalmar Johansens gt. 14, 9007 Tromsø

e-mail: nilu@nilu.no  
nilu-tromso@nilu.no  
Internet: [www.nilu.no](http://www.nilu.no)  
Bank: 5102.05.19030  
Foretaksnr./Enterprise no. 941705561

## EMEP – 34<sup>th</sup> intercomparison of analytical methods

Laboratory 204, Institute for Public Health "Pomoravlje" Cuprija (Republic of Serbia)

### Sulphur dioxide in absorbing solution (A-samples)

Sample name	Determinand	Reported value <sup>¥</sup>	Expected value	Mean value	Standard deviation	Z score	EMEP quality norm <sup>¤</sup>
A2	SO <sub>2</sub>	0.875	0.802	0.779	0.039	2.494	S
A3	SO <sub>2</sub>	0.994	0.842	0.794	0.02	9.791	Q
A4	SO <sub>2</sub>	0.685	0.401	0.387	0.018	16.361	U
A5	SO <sub>2</sub>	0.399	0.441	0.416	0.016	-1.079	S

<sup>¥</sup> Reported values are blank corrected, unless you informed us that this has already been done.  
 Corrections are done by subtracting the blank value when a value was reported, or 1/2 MDL when MDL was reported.

<sup>¤</sup> EMEP quality norm; the letters in the column indicates:

S – Satisfactory: Your result deviates less than  $\pm 10\%$  of the expected value

Q – Questionable: Your result deviates between  $\pm 10\text{--}20\%$  of the expected value

U – Unsatisfactory: Your result deviates more than  $\pm 20\%$  of the expected value

B – Blank: You reported either no value or the detection limit

Please check the EMEP intercalibration website for more statistics, Youden plots, updated expected values ect: <http://www.nilu.no/projects/ccc/intercomparison.html>

*Deltaker i CIENS og Framsenteret / Associated with CIENS and the Fram Centre  
 ISO-sertifisert etter / ISO certified according to NS-EN ISO 9001/ISO 14001*

NILU – Norsk institutt for luftforskning  
 PO Box 100  
 NO-2027 KJELLER, Norway  
 Phone: +47 63 89 80 00/Fax: +47 63 89 80 50  
 Besøk/visit: Instituttveien 18, 2007 Kjeller

NILU – Norsk institutt for luftforskning  
 Framsenteret / The Fram Centre  
 NO-9296 TROMSØ, Norway  
 Phone: +47 77 75 03 75/Fax: +47 77 75 03 76  
 Besøk/visit: Hjalmar Johansens gt. 14, 9007 Tromsø

e-mail: nilu@nilu.no  
 nilu-tromso@nilu.no  
 Internet: [www.nilu.no](http://www.nilu.no)  
 Bank: 5102.05.19030  
 Foretaksnr./Enterprise no. 941705561